

S E R V I C E N O T E

SUPERSEDES: 4195A-18

4195A Network/Spectrum Analyzer

Serial Numbers: 0000A00000 / 9999A99999
0000J00000 / 2904J03253

Duplicate Service Notes:

4194A-14A

4195A-18A

Modification to prevent hang-up at power-on when the instrument is cold**To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

P/N	Description	Qty.
1820-7677	IC,SN74BCT2244N	1

Situation:

The instrument may hang up when it is turned on, because the clock signal in the A6 board might be undershooted. The symptom occurs when the temperature is low, but it won't occur when the instrument is warmed up.

Solution/Action:

Replace the A6U58 from 1820-3145 to 1820-7677.

DATE: October 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: Labor 2.0 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: February 1997
AUTHOR: KW	ENTITY: 3355	ADDITIONAL INFORMATION:	

