

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

54830B-07

S E R V I C E N O T E

Supersedes:
None

54830B Infiniium Oscilloscope – 4 GSa, 2 Ch, 600 MHz

Serial Numbers:

MY41002042

MY41002043

MY41002045

MY41002046

MY41002048

MY41002049

Due to a manufacturing defect, a few probe interface boards may fail.

Parts Required:

P/N	Description	Qty.
54810-66506	Probe Interface Board	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: KO PRODUCT LINE: 1A

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2004
PRINTED IN U.S.A.



Agilent Technologies

May 10, 2004

Situation:

Due to a manufacturing defect, a few probe interface boards may fail. The symptom will be that the oscilloscope will not ID probes correctly.

Solution/Action:

If the oscilloscope is under warranty, replace the probe interface board.

If the oscilloscope is out of warranty, verify that the serial number of the oscilloscope is listed on the first page of this service note. If the serial number is listed, then check the serial number on your warranty data base to see if the probe interface board was previously replaced.

If the probe interface board was previously replaced, then the customer pays for the replacement probe interface board. If the probe interface board was never replaced before, then replace the probe interface board and charge the cost of material and labor to extended warranty.