INFORMATION ONLY - DOES NOT COMMUNICATE A MODIFICATION OR SAFETY CONDITION

54835A-08

SERVICE NOTE

Supersedes: None

54835A Infiniium Oscilloscope 1.0 GHz,4ch, 4 GSa/s

Serial Numbers: MY40000382 - MY40009999

Infiniium Units that are shipped with Acquisition board number 54835-66538 will have problems storing the calibration cal-factors, with system firmware A.04.30. Units will pass User Self-calibration, but if the unit's power is cycled the cal-factors will not be saved, and the unit will be un-calibrated.

These units will be shipping from the factory with the Recovery Software Pouch version A.04.30, and Upgrade system firmware A.04.36. If these units need their Hard Drive re-ignited (Recovered) then the procedure shall be to do a Recovery using the 54810-68808 (A.04.30), and then an Upgrade to the System software using 54810-68820 (A.04.36).

Parts Required:

| P/N | Description | Qty. |
|-------------|-----------------------------------|------|
| 54810-68808 | Infiniium LS120 Recovery Software | 1 |
| 54810-68820 | Infiniium Upgrade Software | 1 |

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: | | |
|------------------------------|------------------|--|
| INFORMATION ONLY | | |
| AUTHOR: MR | PRODUCT LINE: 1A | |
| ADDITIONAL INFORMATION: | | |

© AGILENT TECHNOLOGIES, INC. 2002 PRINTED IN U.S.A.



April 25, 2002

Page 2 of 2 54835A-08

Situation: Infinium Units that are shipped with Acquisition board number 54835-66538 will have problems storing the calibration cal-factors with firmware revision A.04.30. Units will pass User Self-calibration, but if the unit's power is cycled the cal-factors will not be saved, and the unit will be un-calibrated.

Solution/Action:

The Infiniium scopes that are manufactured with the 54835-66538-acquisition board will require the system firmware version A.04.36 to operate correctly. These units will be shipping from the factory with the Recovery Software Pouch version A.04.30, and Upgrade system firmware A.04.36. If these units need their Hard Drive re-ignited (Recovered) then the procedure shall be to do a Recovery using the 54810-68808 (A.4.30), and then an Upgrade to the System software using 54810-68820 (A.4.36).