

S E R V I C E N O T E

SUPERSEDES: None

89410A Vector Signal Analyzer

Serial Numbers: 0000A00000 / 3346A00437

Analyzers may fail radiated emissions requirement due to missing gaskets**To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

Part No.	Qty.	Description
8160-0360	3	Rope Gasket

Situation:

The 3 rope gaskets which should be installed around the front bezel were found to be missing. The purpose of the gasket is to improve the contact between the front frame casting and the covers. The analyzer may fail to meet the radiated emissions requirement without these gaskets.

Continued

DATE: 15 June 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS: Labor 1.0 Hour	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: 15 June 1996
AUTHOR: CMG	ENTITY: A100	ADDITIONAL INFORMATION:	

Solution/Action:

Install gaskets.

STEP 1. Remove top, side, and bottom covers.

STEP 2. Add rope gaskets around the front frame.

1. Press 1 rope gasket into the bottom of the front frame (MP402).
2. Press 1 rope gasket into the top of the front frame.
3. Cut 1 rope gasket in half.
4. Press 1/2 rope gasket into each side of the front frame.

STEP 3. Replace covers.