

S E R V I C E N O T E

SUPERSEDES: None

E1352A 32 Channel Single-ended FET Multiplexer

Serial Numbers: 3035A00101 / 3035A00119

Modification to prevent high environmental noise from causing random errors and disrupting bus communications.

To Be Performed By: Agilent-Qualified Personnel

Duplicate Service Notes:

- E1351A-01
- E1352A-01
- E1353A-01
- E1357A-01
- E1358A-01

Parts Required: Jumper Wire (22 gauge or equivalent)

Situation:

The E1352A is sometimes susceptible to environmental noise which can initialize RAM improperly and cause random errors.

Continued

DATE: 01 June 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.5 Hour		
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: June 1993			
AUTHOR: KD	ENTITY: 0900	ADDITIONAL INFORMATION: Internal reference PCO 09-28409			

One symptom is an invalid “busy” state, disrupting normal bus communications. This may cause error messages such as “IRQ SWITCH SET WRONG” or “FAILS ‘BUSY’ TEST”.

Solution/Action:

To prevent the above condition from causing a problem, ground the enable line on U3 as follows:

CAUTION:

The E1352A contains static-sensitive devices. Use an approved ESD safe workstation for this modification!

On the circuit side of the E1351-26501 board, using a jumper wire, connect pin 7 of U3 to pin 14 of U3 (circuit ground).