

S E R V I C E N O T E

SUPERSEDES: None

E1401A VXI C-Size High-Power Mainframe

Serial Numbers: 3227A00165 / 3227A00207

Possible Shock Hazard



Buildup of surface contamination inside the E1401A power supply plus a jumper wire with damaged insulation may cause a shock hazard to exist on an externally-accessible pin on the rear panel of the E1401A mainframe.

Parts Required:

Part No.	Qty.	Description
E1401-69201	1*	Power Supply (Exchange Assembly)

* Note: This part may not be required. (See text)

Continued

DATE: 06 April 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
SAFETY		
ACTION CATEGORY:	<input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR: 1.0 Hour
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	ALWAYS	USED PARTS: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: KD	ENTITY: 0900	AGILENT RESPONSIBLE UNTIL: ALWAYS
ADDITIONAL INFORMATION:		

Situation:

A situation may exist in which an E1401A in the referenced serial number range could possibly become a shock hazard to personnel. This situation would likely only occur if two conditions BOTH exist internal to the E1401A power supply:

1. There is a buildup of surface contamination on a PC board that could result in a low impedance path for high voltage to a signal wire that is user-accessible on a connector pin on the rear panel of the mainframe.
2. A modification by the manufacturer was not correctly performed.

The shock hazard would then only be present if the user has a cable assembly connected to the Sub-D connector on the rear panel of the mainframe and pin #23 on that cable assembly was openly exposed to personnel.

Solution/Action:

Every E1401A mainframe in the referenced serial number range that comes in for service should be inspected for the failure condition as follows:

Connect a voltmeter between chassis ground and pin #23 on the Sub-D connector on the rear of the E1401A Mainframe. If a hazardous AC Voltage is present (greater than 30 VAC RMS, or 42 VAC Peak), then take the following action:

1. Turn off power to the mainframe and remove the power cord from the power supply.
2. Remove the power supply from the mainframe as follows:
 - a. Using a torx T10 screwdriver, remove the seven screws securing the power supply to the mainframe. (Note: Two of the screws are also holding the two plastic "feet" in the upper corners of the E1401A rear panel.)
 - b. Grasp the two large rings on the power supply and remove it from the frame.
3. Order a replacement power supply (p/n E1401-69201) and install it in the mainframe.
4. Attach a note to the defective power supply stating that it is defective as described in service note E1401A-02. Return the defective unit to the supplier of the exchange assembly for credit.