

## S E R V I C E N O T E

SUPERSEDES: NONE

**E1610A 34 Mb/s E3 Line Interface for Broadband Series****Serial Numbers:** AU3336450 / AU40080500**Errors generated in 34M PLPC Mode****To Be Performed By:** Agilent-Qualified Personnel**Parts Required:** 1821-0992 XC4005 FPGA**Situation:**

Errors generated in 34M PLPC Mode

**Part Affected** Part Number: 1821-0992**Solution / Action:**

Instructions.

To determine if the E1610A has the faulty part do the following test

1. Start the BSTS system with the E1610A loaded. From the TSM select:

AAL1  
 ATM  
 34M PLCP  
 34M PDH

*Continued*

DATE: August 2000

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR 2.0 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: January 2001
AUTHOR: DG	ENTITY: 0Y900	ADDITIONAL INFORMATION: To be done before downloading firmware	

2. Start the BSTS Application.

**From the E1610A Control panel.**

Select Configure Interface

Select Near End Loopback (Right Test Function Button)

Check that there are no RED alarm indicators on the control panel and all are either ghosted or green.

**Set the following statistics.**

Selected Cell Count

Corrected Headers


Cell Loss Count

Bad headers

Sequence Number Error

3. Start a 10 minute measurement and check that the cell count reading is incrementing and all other statistics are zero after the 10 minute integration period.

If the above stats are NOT zero carry out the modification below.



**Figure 1. Location of screws and U31**

**Part Replacement**

- (1) Undo the torx screws on the top shield of the module and loosen or remove the front panel screws as needed to remove the top shield.
- (2) Remove the U31 as identified in the diagram above and exchange it with the replacement part
- (3) Run the system download utility to reload the firmware into the module. (This is performed from the system mainframe using the media supplied with the system.)