

S E R V I C E N O T E

SUPERSEDES: 1682A-02

E1682A SONET/SDH SPE Receiver**Serial Numbers:** AU31160000 / AU31169999**Firmware Revisions:** A.01.00**STM Byte Readback 1 column out of alignment for certain pointer values.****Situation:**

On all instruments, when in STM1 modes, the byte readback is out of alignment by column with respect to the current pointer value. This is only the case for values one less than multiples of 87. Thus 86, 173, 260, etc. The effect of this is that for those pointer values PBIP errors will be generated because of corruption of the Path Overhead.

Solution/Action:

Install current upgrade firmware. This is automatically shipped to users at regular intervals. If remedy is required urgently, contact Australian Telecom Operation

PH +61 3 2722795
FAX +61 3 8989257

Parts Required:

Series 90 firmware upgrade disk.

DATE: 31 October 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor:
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	Next Firmware Upgrade	AGILENT RESPONSIBLE UNTIL: October 1993	
AUTHOR: DGH	ENTITY: Y900	ADDITIONAL INFORMATION:	

