

E5071C-28**S E R V I C E N O T E**Supersedes:
NONE**E5071C ENA Series Network Analyzer, 9 kHz to 20 GHz****Serial Numbers: MY46212347 to MY46214506, SG46200264 to SG46200284****Automatically shut down after a few seconds beeping occurs when user turns on the instrument****Parts Required:**

P/N	Description	Qty.
3160-4452	CPU fan	1
E5070-62060	COM-express CPU module	1
E5071-61680	interface cable	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY☐ Calibration Required☒ Calibration NOT Required

PRODUCT LINE: WN

AUTHOR: jm

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2013

PRINTED IN U.S.A.

January 2, 2014

Rev. 21

**Agilent Technologies**

Page 1 of 4

Situation:

Automatically shut down after a few seconds beeping occurs when user turns on the instrument.
This is due to CPU Fan rotor dropped off or CPLD on CPU board is broken.

Solution/Action:

Trouble isolation and action needed



1. Push down CPU fan's rotor using something like tooth pick just after turning on power switch.



2. If CPU fan rotates, then the cause of the trouble is [dropped off rotor]





2-1. Check whether connector post (J19) for the CPU fan's interface cable is the correct direction or the opposite (incorrect) direction as shown below.



2-2. If black wire of the CPU fan cable is next to the nearby screw, J19 is assembled in a correct way.
In this case, just replace CPU fan with a new one (3160-4452) for repair.

2-3. If yellow wire of the CPU fan cable is next to the nearby screw, J19 is assembled in an incorrect way.
In this case, disconnect the CPU fan cable from J19 and measure CPLD voltage of the pin



2-3-1. If the voltage is less than 1.2V, CPLD circuit of the CPU carrier board is damaged.
In this case, replace whole CPU assembly with E5070-62060.

2-3-2. If the voltage is greater than 1.5V, the circuit of the CPU carrier board is OK.
In this case, replace CPU fan and interface cable with 3160-4452 and E5071-61680.

3. If CPU fan does not rotate when rotor is pressed down lightly even when POST LED turned on and it proceeded from 00, check if the voltage of the red wire of the fan is 12V.

3-1. If +12V is supplied to the red wire, then most suspicious cause is CPU fan itself.

3-1-1. If the interface cable is incorrect wire position,
in this case, replace CPU fan and interface cable with 3160-4452 and E5071-61680.

3-1-2. If the interface cable is correct wire position,
in this case, replace CPU fan with 3160-4452.

- 3-2. If +12V is not supplied to the red wire, check if CPU carrier board is OK or check if power supply can be started.

Revision History:

Revision Number	Date	Author	Reason For Change
E5071C-28	31-Dec-2013	jm	As published