

E8358A-06A

S E R V I C E N O T E

Supersedes:
E8358A-06

E8358A PNA Series RF Network Analyzers

Serial Numbers: US000000000/US999999999 and MY000000000/MY999999999

Replace Inverter board (0950-3379) due to faulty component.

To Be Performed By: Agilent-qualified personnel or customer with specific product repair knowledge - requires instrument disassembly and component replacement.

Parts Required:

P/N	Description	Qty.
0950-3379	DC/AC Inverter Board	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	IMMEDIATELY ON SPECIFIED FAILURE X AGREEABLE TIME	STANDARDS	LABOR: 0.2 Hours
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE X ON-SITE X SERVICE CENTER	SERVICE INVENTORY:	RETURN X SCRAP SEE TEXT
		USED PARTS:	RETURN X SCRAP SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: ALWAYS	
AUTHOR:	MF	PRODUCT LINE: WN	
ADDITIONAL INFORMATION: Affected PNA models: E8356/7/8A, E8801/2/3A, N3381/2/3A, N5230A, E8361/2/3/4A, E8362/3/4B. Service Note History: -06a, April 08, Change from Mod. Available to Mod. Recommended.			

© AGILENT TECHNOLOGIES, INC. 2008
PRINTED IN U.S.A.

April 29, 2008

Rev. 14



Situation:

The original fuse (see photo) in the DC/AC Inverter board (p/n 0950-3379) is prone to failure in normal use.

Solution/Action:

Replace the Inverter board with a board containing the new fuse (see photo).

