

MODIFICATION RECOMMENDED

E8663D-01

S E R V I C E N O T E

Supersedes:
None

E8663D Analog Signal Generator

Serial Numbers:

MY00000000/MY49281586, SG00000000/SG49280245 and US00000000/US49280498

Intermittent CPU boot-up and/or No display

Parts Required:

P/N	Description	Qty.
None		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	x ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 0.5 Hour
LOCATION CATEGORY:	x CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE x SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	Always	NO CHARGE AVAILABLE UNTIL: 2/14/2013	
AUTHOR:	SN	PRODUCT LINE: 15	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2011
PRINTED IN U.S.A.

February 11, 2011

Rev. 18



Situation:

The clock buffer, U7 on the CPU board (E8251-60006 or E8251-60661), may cause intermittent boot up and/or no display when the instrument is powered up. It is recommended that this modification is performed on any instrument within the serial numbers above that exhibits an intermittent boot-up and/or a blank display.

Solution/Action:

Using the appropriate soldering technique and ESD station, perform a modification on the U7 circuit on the CPU board. Connect U7 pin 8 to 3.4V (wire pin 8 to pin 4) and connect U7 pin 9 to DCOM (wire pin 9 to pin 12).

U7 modification procedure:

1. Refer to E8257D Service Guide for the A18 CPU removal procedure.
2. Refer to Figure 1 for U7.
3. Use 30 AWG wire for wiring pin 8 to pin 4, and pin 9 to pin 12 per Figure 1.
4. Re-install CPU and cover.
5. Run self test.
6. No calibration is required.

Figure 1 U7 wire modification

