

**S E R V I C E N O T E**

Supersedes:  
NONE

L4451A 4-Channel LXI isolated D/A converter with waveform memory

Serial Numbers: MY46100199-MY46100220  
MY47000003  
SG46100111

**Relay contact contamination causes variation in performance.**

**Parts Required:**

P/N	Description	Qty.
L4451-80001	4-Chan DAC w/o GPIB	1
or		
L4451-80002	4-Chan DAC w/GPIB	1

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 0.5 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 7/1/2014	
<input type="checkbox"/> Calibration Required <input checked="" type="checkbox"/> Calibration NOT Required	PRODUCT LINE: BL AUTHOR: TP		
ADDITIONAL INFORMATION: Used parts are to be returned to factory for failure analysis.			

**Situation:**

It has been found that affected L4451A modules described above may have contaminated relays contacts within the high current protection circuits that can cause intermittent variation in the modules specifications.

- This could limit the available output amplitude to  $\pm 14\text{V}$  instead of  $\pm 16\text{ V}$  when driving the full rate output current of  $\pm 10\text{ mA}$ .
- The DC voltage amplitude accuracy could be degraded to  $\pm(0.05\% + 2.003\text{V})$  instead of  $\pm(0.05\% + 3\text{mV})$ .
- The DC current compliance voltage limit could be reduced from  $\pm 12\text{V}$  to  $\pm 8\text{V}$  at the rated output current of  $\pm 20\text{mA}$ .

**Solution/Action:**

If these symptoms are observed, contact Agilent Service for a replacement.

**Revision History:**

Revision Number	Date	Author	Reason For Change
1.0	6/7/13	TP	As Published