N1996A-05 S E R V I C E N O T E

Supersedes: NONE

N1996A Agilent CSA Spectrum Analyzer

Serial Numbers: ALL

Stick antistatic tape on W8 Flex circuit to improve the connection reliability

Parts Required:

P/N Description Qty.

0460-2222 Red antistatic tape 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY::	AGREEABLE TIME	[[]] PERFORMANCE ENHANCEMENT X SERVICE / RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER [[]] CHANNEL PARTNERS	AVAILABILITY: Support Life
AUTHOR: Jian Kang		PRODUCT LINE: CM
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2010 PRINTED IN U.S.A.



Page 1 of 3


April 16, 2010

Rev. 17

Page 2 of 3 N1996A-05

Situation:

The instrument display color may change due to lose connection of Flex circuit W8 on A2 Processor assembly.



An antistatic tape is available to improve the connection reliability of the Flex circuit.


When the display color is abnormal or any of the below assembly is replaced, use the antistatic tape to improve the connection reliability.

W8 Flex Circuit A
W9 Flex Circuit B
A3 Power Supply Assembly
A2 Processor Assembly


Solution/Action:

Refer to the N1996A Service Guide on page 124 to remove the A2/A3 Processor and Power Supply assembly.


2. Stick 0460-2222 anti static red tape close to the W8 Flex Circuit A with a length of 90mm from position 1 to the bottom of the flex as indicated by the arrow.



Page 3 of 3 N1996A-05



3. Ensure that the connection at J2 on Processor Assembly is tightly secured with no gap. The picture as below is rejected.





Notes: Do not RECYCLE the red tape.