

N3382A-04**S E R V I C E N O T E**Supersedes:
NONE**N3382A PNA Series RF Network Analyzers****Serial Numbers: 0000A00000/9999Z99999 [All]****Replace Inverter board (0950-3379) due to faulty component.****To Be Performed By: Agilent-qualified personnel or customer with
specific product repair knowledge - requires
instrument disassembly and component replacement.****Parts Required:**

<u>P/N</u>	<u>Description</u>	<u>Qty.</u>
0950-3379	DC/AC Inverter Board	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	X AGREEABLE TIME	PERFORMANCE ENHANCEMENT X SERVICE / RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE* X ON-SITE X SERVICE CENTER	AVAILABILITY: Support Life
AUTHOR: MF PRODUCT LINE: WN		
ADDITIONAL INFORMATION: *See "To Be Performed By." Written 10/17/07. Affected PNA models: E8356/7/8A, E8801/2/3A, N3381/2/3A, N5230A, E8361/2/3/4A, E8362/3/4B.		

© AGILENT TECHNOLOGIES, INC. 2007
PRINTED IN U.S.A.

October 18, 2007

