

MODIFICATION RECOMMENDED

**N9936A-01**

**S E R V I C E N O T E**

Supersedes:  
None

**N9936A - FieldFox Handheld Analyzer**

**Serial Numbers:** Listed at end of note.

**FieldFox instruments with the serial numbers listed on the following page are being returned to Agilent factory so the RF board can be upgraded for reliability enhancement, due to possible oscillation by the voltage regulator on the RF board.**

**Parts Required:**

P/N	Description	Qty.
None		

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION: <b>MODIFICATION RECOMMENDED</b>		
ACTION X ON SPECIFIED FAILURE CATEGORY: <input type="checkbox"/> AGREEABLE TIME	STANDARDS LABOR: 3.0 Hours	
LOCATION X SERVICE CENTER <b>(RETURN TO FACTORY)</b> CATEGORY:	SERVICE <input type="checkbox"/> RETURN INVENTORY: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED <input type="checkbox"/> RETURN PARTS: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 18 April 2014	
X Calibration Required <input type="checkbox"/> Calibration NOT Required	PRODUCT LINE: WN AUTHOR: DYCS	
ADDITIONAL INFORMATION: <b><u>UNIT MUST BE RETURNED TO FACTORY FOR REPAIR.</u></b>		

© AGILENT TECHNOLOGIES, INC. 2013  
PRINTED IN U.S.A.

March 21, 2013

Rev. 21



**Situation:**

RF board earlier than Rev 7 may have sidebands issue due to oscillation by the voltage regulator. After it is fixed by replacing a new inductor, the RF board revision header will be updated to reflect the change.

Figure 1 shows a good RF signal, and Figure 2 shows FieldFox with sidebands issue.

Figure 1: No sidebands issue





Figure 2: Sidebands issue between 112 - 116 kHz



**Solution/Action:**

Follow below procedure to check if the FieldFox may have sidebands issue between 112 kHz to 116 kHz.

1. Press Mode, select SA
2. Press Freq/Dist, set center frequency as 0 Hz, Span: 1 MHz.
3. Press BW, set Res BW: 100Hz, and Video BW: 100 Hz

Affected FieldFox are required to send back to Agilent factory for RF board reliability enhancement. The RF board revision header will be updated to reflect the change. Test and Adjustment shall be done before shipping back to customer.

	Serial Number
1	US52240363
2	US52240364
3	US52240365

**Revision History:**

Revision Number	Date	Author	Reason For Change
1.0	3/18/13	DYCS	As published