

S E R V I C E N O T E

SUPERSEDES: None

18283A ISDN Interface Pod

Serial Numbers: 3023A00000 / 3023A00155

Misloaded Capacitors

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Part No.	Description	Qty.
18283-69502	Frame/PreAmp Assy	1

Situation:

It was discovered that several capacitors on the two boards that make up the 18283A have been loaded backward. Over time the capacitors will begin to breakdown, overheat and smoke

Solution/Action:

An exchange assembly has been setup to allow for a quick method of replacing the defective boards. This assembly is made up of both boards that are in the 18283A interface pod. Use the exchange assembly, p/n 18283-69502, to fix the misloaded capacitor problem.

DATE: 26 November 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input checked="" type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.80 hrs
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: RCB	ENTITY: 3800	RESPONSIBLE ENTITY: 3800	UNTIL: 01 January 1994
		ADDITIONAL INFORMATION:	