

MODIFICATION RECOMMENDED

33220A-03

**S E R V I C E N O T E**

Supersedes:  
None

33220A 20 MHz Function/Arbitrary Waveform Generator

Serial Numbers: MY44043922/MY44044188

**Flatness Calibration Error**

**Parts Required:**

P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 1.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: September 2010	
AUTHOR:	LH	PRODUCT LINE: SP	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2009  
PRINTED IN U.S.A.

August 24, 2009

Rev. 16



**Situation:**

Agilent has recently discovered an error during flatness calibration for the units with the serial numbers listed in the table below. If your serial number is not located in this table then your unit was not affected and this service note does not apply.

MY44043922
MY44043996
MY44043999
MY44044005
MY44044009
MY44044011
MY44044013
MY44044126
MY44044148
MY44044150
MY44044157
MY44044158
MY44044165
MY44044185
MY44044188

**Solution/Action:**

We recommend the unit be sent to the nearest local service center for a FREE recalibration.