

**34932A-02**

**S E R V I C E N O T E**

Supersedes:  
NONE

**34932A Dual 4x16 Armature Matrix Module for 34980A**

**Serial Numbers:** MY43000190  
MY44002447  
MY44002571-MY44003152  
MY45000003-MY45000086

**Intermittent contact resistance with Analog Bus (ABus) relays.**

**Parts Required:**

P/N	Description	Qty.
34932-60001	Dual 4x16 Armature Matrix new replacement unit	1

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:		<b>MODIFICATION RECOMMENDED</b>	
ACTION CATEGORY:	<input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 0.5 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 7/1/2014	
<input type="checkbox"/> Calibration Required <input checked="" type="checkbox"/> Calibration NOT Required		PRODUCT LINE: BL AUTHOR: TP	
ADDITIONAL INFORMATION: Used parts are to be returned to factory for failure analysis.			

© AGILENT TECHNOLOGIES, INC. 2013  
PRINTED IN U.S.A.

June 7, 2013

Rev. 20



**Situation:**

The ABus relays used in these affected 34932A modules may exhibit intermittent high contact resistance. This can affect two wire resistance measurements and can cause excessive voltage drop in sensitive signal routing applications.

**Solution/Action:**

If these symptoms are observed, contact Agilent Service for a replacement.

**Note:**

- New specifications apply to module replacement with serial number MY52490001/SG52490001 and above. Please refer to the 34980A datasheet in the product website (<http://www.agilent.com/find/34980A>) for latest specifications.
- If you use Y1131A verification software version 1.0, July 2005, please update to the latest version at the Y1131A product website (<http://www.home.agilent.com/en/pd-1383501-pn-Y1131A/verification-and-diagnostic-tools?nid=-33253.778753.00&cc=US&lc=eng>) to test to the latest specifications.

**Revision History:**

Revision Number	Date	Author	Reason For Change
1.0	6/7/13	TP	As Published