

34939T-01

# Modification Recommended Service Note

Supersedes:  
NONE

## 34939T Terminal Block for 34939A 64-Channel Form A Switch

Serial Numbers: ALL

The Problem – Unable to connect to mating connector

### Parts Required:

P/N	Description	Qty.
34939-60002	Terminal Block for 34939A 64-Channel Form A Switch	1

### ADMINISTRATIVE INFORMATION

ACTION	<input checked="" type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS		
CATEGORY:	<input type="checkbox"/> AGREEABLE TIME	LABOR:	0.25 Hours	
LOCATION	<input type="checkbox"/> CUSTOMER INSTALLABLE	SERVICE:	<input type="checkbox"/> RETURN	USED <input type="checkbox"/> RETURN
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	<input type="checkbox"/> SCRAP	PARTS: <input checked="" type="checkbox"/> SCRAP
	<input checked="" type="checkbox"/> SERVICE CENTER		<input checked="" type="checkbox"/> SEE TEXT	<input type="checkbox"/> SEE TEXT
	<input type="checkbox"/> CHANNEL PARTNERS			
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	02 May 2023	
	<input type="checkbox"/> Calibration Required	PRODUCT LINE:	GM	
	<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR:	ML	

ADDITIONAL INFORMATION:

**Situation:**

Due to pin misalignment inside the 78-pin D-sub connector, there will be difficulty or unable to connect the terminal block to its mating connector.

**Solution/Action:**

If you have difficulty or unable to connect your terminal block to its mating connector, kindly contact Keysight Customer Contact Center at [www.keysight.com/find/contactus](http://www.keysight.com/find/contactus) to return the terminal block and get a new replacement part.

**Revision History:**

Date	Service Note Revision	Author	Reason for Change
30 April 2022	01	MonikaaLisa	As Published