

## S E R V I C E N O T E

SUPERSEDES: None

**37732A Telecom Datacom Analyser****Serial Numbers:** 0000U00000 / 9999U99999**Faulty Datacom Lid****Situation:**

Recently there have been instances of the Datacom Lid p/n 15901-60001 being returned to the Division apparently faulty. This has not been the case. The dual in-line switch S1 has been set wrongly.

**Solution / Action:**

Set all switches in S1 CLOSED, that is with the lever depressed on the right hand side of the board. This is correct for the instrument's factory settings. Only move these switches when instructed to do so for specific tests. This will reduce the chances of "non-faulty" instruments being returned to the Division in error.

DATE: September 1997

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR:

GS

ENTITY:

E600

ADDITIONAL INFORMATION:

