

S E R V I C E N O T E

SUPERSEDES: None

4286A RF LCR Meter

Firmware Revision: Rev. 2.01

Firmware Upgrade to Correct Compensation ON/OFF Problem**To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

| P/N | Description | Qty. |
|-------------|-------------------------------------|------|
| 04286-65013 | Firmware Installation Kit Rev. 2.02 | 1 |

Situation:

In the 4286A firmware revision 2.01 and below, the OPEN/SHORT/LOAD compensation on/off state cannot be saved/recalled in the STATE file when the FIXTURE type is set to USER.

Solution/Action:

Upgrade the firmware to revision 2.02 using the installation kit. For installation procedure, refer to the manual provided with the installation kit.

DATE: June 1996

ADMINISTRATIVE INFORMATION

| | | | |
|---------------------------------|--|--------------------------------------|--|
| SERVICE NOTE CLASSIFICATION: | | | |
| MODIFICATION RECOMMENDED | | | |
| ACTION CATEGORY: | <input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME | STANDARDS: | Labor 0.5 Hour |
| LOCATION CATEGORY: | <input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER | SERVICE INVENTORY: | <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | USED PARTS: | <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT |
| AUTHOR: YM | ENTITY: 3355 | AGILENT RESPONSIBLE UNTIL: June 1998 | |
| | | ADDITIONAL INFORMATION: | |