

S E R V I C E N O T E

SUPERSEDES: NONE

HP 4291B RF Impedance/Material Analyzer

Serial Numbers: JP1KE00101 / JP1KE00166

Modification to fix a intermittent display problem

To Be Performed By: HP-Qualified Personnel

Parts Required:

HP P/N	Description	Quantity
E4970-66554	GSP board	1

Situation:

Nothing (all white image) is displayed on LCD intermittently after turning on the instrument. This problem may be caused by faulty of GSP board with HP part number E4970-66552.

Solution / Action:

This problem will be fixed by GSP board replacement from E4970-66552 to E4970-66554.

DATE: July 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 1.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> HP LOCATION	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: AY	ENTITY: 3355	HP RESPONSIBLE UNTIL: July 2000	
		ADDITIONAL INFORMATION:	