# S E R V I C E N O T E

SUPERSEDES: 4352B-01B

# 4352B VCO/PLL SIGNAL ANALYZER

Serial Numbers: JP1KE00101 / JP1KE00195

# Replacement for obsoleted LCD P/N 2090-0534

To Be Performed By: Agilent-Qualified Personnel

## Parts Required:

P/N	Description	Quantity
2090-0574	LCD 8.5 INCH	1
E4970-61651	FLAT CBL FFC	1
E4970-04002	COVER	1
E4970-66539	LCD MINI-BD	1
0400-0010	GROM-RND	1
04396-25071	GASKET	1
0515-1550	SCR M3-L 8 P-H	1

#### **Situation:**

The LCD P/N 2090-0534 has been obsoleted and not available any more.

#### **Solution / Action:**

When the LCD P/N 2090-0534 become defective, new replacement LCD P/N 2090-0574 must be used and the parts listed above are also needed. See the Replaceable Parts section of the 4352B Service manual (Edition 1) for more details and assembly procedures.

DATE: July 1998

## **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:  INFORMATION ONLY			
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:	
HN	3355		

© 1998 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

