

## S E R V I C E N O T E

SUPERSEDES: None

**44477A Form C Relay**

**44487A Terminal Block shipped with 44477A Relay Module used with Agilent 3499A/B or 3488A Switch Systems.**

**WARNING****Possible Shock Hazard**

**Customer wiring utilizing incorrect silkscreen may create potential shock hazard or equipment damage.**

**Serial Numbers:** Not applicable. Affected product range can be traced by Shipment Date.

**Shipment Date:** From September 1st, 2000 to February 28th, 2001.

**To Be Performed By:** Customer

**Parts Required:**

Agilent P/N	Description	Quantity
44487A	Terminal Block	1

*Continued*

DATE: March 2001

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**SAFETY**


ACTION CATEGORY:		<input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME		STANDARDS:		LABOR 0.5 Hours	
LOCATION CATEGORY:		<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER		SERVICE INVENTORY:		<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	
AVAILABILITY:		ALWAYS		USED PARTS:		<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	
AUTHOR: AT		ENTITY: Y500		AGILENT RESPONSIBLE UNTIL : ALWAYS			
				ADDITIONAL INFORMATION:			

© 2000 AGILENT TECHNOLOGIES  
 PRINTED IN U.S.A.

**Agilent Technologies**

**Situation:**

Some Agilent 44487A Terminal Blocks shipped with Agilent 44477A Relay Modules have incorrect silkscreen printing. On the incorrect terminal blocks the silkscreen printing is shifted from the correct position. The silkscreen printing on correct parts should correspond to the connector holes. Please see the below photo.



**Figure 1. Picture of the Terminal Block**

**Solution / Action:**

Agilent will replace the incorrect Terminal Block (44487A) with a correct one.

Service Inventory is not affected.