

S E R V I C E N O T E

SUPERSEDES: None

54750A Digitizing Oscilloscope**Serial Numbers:** 0000A00000 / 9999Z99999**Plug-in vertical calibration failures on 83480A option 100 mainframes****Duplicate Service Notes:** 83480A-02**To Be Performed By:** Agilent-Qualified Personnel**Situation:**

If option 100 is installed in the mainframe, the plug-in vertical calibration will fail if the enhanced trigger mode is selected.

Solution / Action:

Before attempting the plug-in vertical calibration (Utility/Calibrate Calibrate plug-in....select plug-in and start cal), Select Trigger/ Trig Bandwidth/DC - 2.5 GHz. The vertical calibration will fail if trigger bandwidth 2 - 12 GHz or 2 - 12 GHz Gate is selected. This does not mean there is a problem with the plug-in module.

DATE: March 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

BH

ENTITY:

5360

ADDITIONAL INFORMATION:

