S E R V I C E N O T E

SUPERSEDES: None

83215B PHS RF Interface

Serial Numbers: 0000A00000 / JP2KC00166

Duplicate Service Notes: 83215A-04

Incorrect relay may be installed

To Be Performed By: HP-qualified personnel

Situation:

Incorrect relay may be installed in the instrument serialized above. It will not affect any instrument performance.

Wrong part number HP 8765A OPT 015,100

Correct part number HP 8765B OPT 015,100

Solution/Action: None

DATE:March 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
	INFORMAT	TON ONLY
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
YO	3355	

© 1997 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.

