

S E R V I C E N O T E

SUPERSEDES: 83480A-01

83480A Digital Communications Analyzer

Serial Numbers: 0000A00000 / 9999Z99999

Kit to retrofit option 100, 12 GHz trigger**To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

P/N	Description	Quantity
83480-60004	Option 100 retrofit kit	1

Situation:

The above kit is available to retrofit option 100 into an 83480A. It is not available to retrofit 54750A's. Option 100 is not available on the 54750A. This retrofit should be done at the Service Center.

Solution / Action:

The customer should arrange with the service center to have this option installed. The Service Center will order and install the kit and bill time and materials for the retrofit. To install option 100 in the 83480A, get 83480-60004. This consists of a Data Acquisition Assembly, a rear panel, a front panel label, and documentation. Replace these assemblies, perform the mainframe calibration and return together with the manuals to the customer. Be sure to add option 100 to the serial label. Please return the old Data Acquisition Assembly to me so that we can use it in the exchange assembly process.

DATE: January 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY: AGREEABLE TIME		<input checked="" type="checkbox"/> PERFORMANCE ENHANCEMENT <input type="checkbox"/> SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	AVAILABLE UNTIL: September 1999
AUTHOR: BH ENTITY: 5360		ADDITIONAL INFORMATION: