

S E R V I C E N O T E

SUPERSEDES: None

85460A EMC RF Filter Section

Serial Numbers: 0000A00000 / 9999Z99999

EEROM Firmware Upgrade**Duplicate Service Notes:**

85420E-01

85460A-01

Parts Required:

Part No.	Qty.	Description
5063-0688	1	Firmware Kit

Situation:

Replacement firmware provides the following:

- 1) Allows firmware to ID as 8546A or 8542E,
- 2) Moves crossover between paths 24/25 from 1 GHz to 1.03 GHz, and
- 3) corrects a "bug" in EESUM and ROMSUM.

Solution/Action:

At the customer's convenience or when returned to the CSC for repair or calibration, if the firmware revision date is not Rev 94.08.02, then order kit 5063-6088.

DATE: December 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS: Labor 0.5 Hour	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: December 1997
AUTHOR: SPB	ENTITY: 5340	ADDITIONAL INFORMATION:	