

S E R V I C E N O T E

SUPERSEDES: NONE

8644B Synthesized Signal Generator**Serial Numbers:** See Duplicate Service Notes**Return specified transformers to factory for analysis.****Duplicate Service Notes:**

8644B-04 Serials: 3546A00973 / 3546A01081

8645A-05 Serials: 3546A00554 / 3546A00569

8664A-05 Serials: 3546A01174 / 3546A01358

8665A-06 Serials: 3546A00850 / 3546A00873

8665B-04 Serials: 3546A00891 / 3546A01000

To Be Performed By: Agilent-Qualified Personnel**Parts Required:**

P/N	Description	Qty.
9100-4757	Power Transformer	1
2110-0083	Fuse 2.5A 250V	1

Continued

DATE: November 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:		STANDARDS:	
☐ IMMEDIATELY ☒ ON SPECIFIED FAILURE ☐ AGREEABLE TIME		LABOR 2.0 Hours	
LOCATION CATEGORY:		SERVICE INVENTORY:	USED PARTS:
☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☒ SERVICE CENTER		☐ RETURN ☐ SCRAP ☒ SEE TEXT	☐ RETURN ☐ SCRAP ☒ SEE TEXT
AVAILABILITY:		AGILENT RESPONSIBLE UNTIL:	
PRODUCT'S SUPPORT LIFE		May 2000	
AUTHOR: MW		ADDITIONAL INFORMATION:	
ENTITY: 5320			

Situation:

This transformer, in the affected serial number range listed above, has demonstrated a potential reliability problem at the factory, and might blow the main line fuse (P/N 2110-0083) if a properly grounded power cable is not used.

Solution / Action:

It is recommended that any transformer from a power supply that blows its line fuse in the affected instruments be replaced, and the old transformer be returned to the factory for analysis. Warranty is extended for the fuse failure and associated transformer replacement until 1 May, 2000 on all instruments specified above.

Please contact MID Source Support at (707)577-6803 for instructions on returning the transformer.