S E R V I C E N O T E

SUPERSEDES: None

8753ES Option 011 Vector Network Analyzer

08753-90485: 8753ES Option 011 Service Guide

Serial Numbers: All Units

Incorrect Replacement Part for Samplers in Service Guide.

Situation:

The Service Guide for the 8753ES Option 011, 08753-90485, has the incorrect replacement parts for the samplers. The affected Service Guides have print dates of November 1999 and February 2000. On page 13-8, part number 08753-60907 is identified as the replacement part for samplers A4, A5, and A6. The correct part number should be 08753-60951.

Solution / Action:

The Service Guide, 08753-90485, will be corrected and updated at a future print date. The parts centers have been directed to replace samplers for the 8753ES Option 011 with part number 08753-60951 and not 08753-60907.

DATE: October 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
	INFORMATION ONLY	
AUTHOR: FD	ENTITY: 5334	ADDITIONAL INFORMATION:

© 2000 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

