

S E R V I C E N O T E

SUPERSEDES: None

89430A RF Section**Serial Numbers:** 0000A00000 / 9999Z99999**Exchange modules being damaged by using wrong wrench****To Be Performed By:** Agilent-Qualified Personnel or Customer**Parts Required:**

Part No.	Description
89400-65001	Calibrated Wrench

Situation:

The A10 Receiver, A60 Local Oscillator, and A70 Source modules are being damaged by incorrect force being applied when connecting the SMA cables to the modules.

Solution/Action:

Use the wrench specially calibrated for the modules, part number 89400-65001. this wrench replaces the 5/16 inch wrench supplied in the 89430-84401 service kit.

DATE: December 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

MODIFICATION AVAILABLE

ACTION CATEGORY:	AGREEABLE TIME	<input type="checkbox"/> PERFORMANCE ENHANCEMENT <input checked="" type="checkbox"/> SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	AVAILABLE UNTIL: December 1996
AUTHOR: CMG	ENTITY: A100	ADDITIONAL INFORMATION: