

DSOV134A-02A

Modification Recommended Service Note

Supersedes:
DSOV134A-02

DSOV134A Infiniium Oscilloscope: 13GHz

Serial Numbers: MY00000000 / MY55300100

[The Problem – V-series scopes can shut down after the initial power on.

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

ACTION		☐ ON SPECIFIED FAILURE		STANDARDS	
CATEGORY:	X	AGREEABLE TIME		LABOR: 1.0 Hours	
LOCATION	☐ CUSTOMER INSTALLABLE		SERVICE: ☐ RETURN INVENTORY: ☐ SCRAP ☐ SEE TEXT		
CATEGORY:	☐ ON-SITE (active On-site contract required)				
	X	SERVICE CENTER			
	☐ CHANNEL PARTNERS		USED ☐ RETURN PARTS: ☐ SCRAP X SEE TEXT		
AVAILABILITY:		PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: DEC. 01 2019	
	X Calibration Required		PRODUCT LINE PL1A		
	☐ Calibration NOT Required		AUTHOR: MRR		

ADDITIONAL INFORMATION: This action "RTF" should be taken on any failure of the listed serial numbers in effect.

Situation:

V-series scopes can shut down after the initial power on. Units that were originally manufactured had a component on the acquisition assembly loaded that should have not been loaded. The component is L305 and needs to be removed on both acquisition assemblies. V-Series units effected need to be Returned To the Factory for upgrade, please see serial numbers to determine if RTF process is required.

Solution/Action:

– V-series scopes that have serial numbers < MY55300101 if returned to local service centers for repair need to be transshipped to F03 for factory repair.

The factory will remove the L305 and test, calibrate unit to specifications return with Certificate of Calibration.

Revision History:

Date	Service Note Revision	Author	Reason for Change
27 June 2018	01	Mark Rowley	As Published