

MODIFICATION RECOMMENDED –  
CORRECTS MANUFACTURING OR DESIGN DEFECTS

**E5052A-01**

# S E R V I C E N O T E

Supersedes:  
NONE

## E5052A Signal Source Analyzer

Serial Numbers: MY44100101 / MY44100157

**One or two units might have been shipped with wrong keypad rubber**

**To Be Performed By: Agilent-Qualified Personnel**

**Parts Required:**

P/N	Description	Qty.
E5052-25101	Keypad Rubber	1

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR: 0.3 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: KW      PRODUCT LINE: WN		AGILENT RESPONSIBLE UNTIL: Sep 2006	
ADDITIONAL INFORMATION:			


© AGILENT TECHNOLOGIES, INC. 2004  
PRINTED IN U.S.A.



September 21, 2004

**Situation:**

Analyzers specified above might have a wrong keypad rubber.



**Solution/Action:**

Replace the wrong keypad rubber with a correct one.