

MODIFICATION RECOMMENDED –
CORRECTS MANUFACTURING OR DESIGN DEFECTS

E5062A-02A

S E R V I C E N O T E

Supersedes:
E5062A-02

E5062A RF Network Analyzer

Serial Numbers: MY44100207 / MY44100295

One or two units might have been shipped with wrong keypad rubber

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N	Description	Qty.
E5070-25101	Keypad Rubber	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY X ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR: 0.3 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE X SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN X SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: Sep 2006	
AUTHOR: KW		PRODUCT LINE: WN	
ADDITIONAL INFORMATION:			


© AGILENT TECHNOLOGIES, INC. 2004
PRINTED IN U.S.A.



September 21, 2004

Situation:

Analyzers specified above might have a wrong keypad rubber.



Solution/Action:

Replace the wrong keypad rubber with a correct one.