

E5062A-08**S E R V I C E N O T E**Supersedes:
NONE**"E5062A ENA Series Network Analyzer, 300 kHz to 3 GHz"****Serial Numbers: "MY44100001 to MY44205489"****"Source level might decrease gradually and become out of spec."****Parts Required:**

P/N	Description	Qty.
none		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:: AGREEABLE TIME		<input type="checkbox"/> PERFORMANCE ENHANCEMENT <input checked="" type="checkbox"/> SERVICE / RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNERS	AVAILABILITY: Until End Of Support
AUTHOR: jm		PRODUCT LINE: WN
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2009
PRINTED IN U.S.A.

October 29, 2009

Rev. 16

**Agilent Technologies**

Page 1 of 2

Situation:

Source level might decrease gradually and become out of spec.

It might occur whether customer turn on a unit or not.

Solution/Action:

1. Perform the following adjustments by using E5061A/E5062A Performance Test program Version A.02.00 or later.

- ☐ Synthesizer Gain Adjustment
- ☐ Local Output Power Adjustment
- ☐ Source Output Power Adjustment
- ☐ Receiver IF Range Adjustment
- ☐ Receiver Ports Characteristics Adjustment

2. Perform the verification test

- ☐ “To Execute the Diagnostic Test” on page 101 of E5061A/E5062A service manual.
- ☐ Frequency Accuracy Test
- ☐ RF Output Level Accuracy and Flatness Test
- ☐ RF Output Level Linearity Test
- ☐ Trace Noise Test
- ☐ Crosstalk & System Dynamic Range Test
- ☐ Dynamic Accuracy Test
- ☐ Uncorrected System Performance Test

3. If there is a FAIL test, replace A1 Source Board.

If there is no FAIL test, verification is done correctly.

- End of Document -