

S E R V I C E N O T E

SUPERSEDES: None

J2522B Lan Advisor

Serial Numbers: US35300102 - US35310838

New J2522-66504 Network Interface Assembly corrects improper Jam Signal to network

Duplicate Service Notes:

J2522B-02

J2523B-02

Situation:

The J2522-66503 Interface board has a design problem that senses a collision that does not exist. The result of these collision detections is the J2522B will send out a Jam Signal that will cause problems on the customers network over time.

Solution/Action:

Replace all J2522-66503 with the new design J2522-69504 exchange assembly.

DATE: October 1995

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 2.0 Hours		
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: October 1997		
AUTHOR: RM	ENTITY: 3801		ADDITIONAL INFORMATION:		