

MODIFICATION RECOMMENDED

L4491A-03

S E R V I C E N O T E

Supersedes:
NONE

L4491A 4U RF/Microwave Switch Platform

Serial Numbers: MY00000000 through MY53500421

Instrument cannot operate in 400 Hz

Parts Required:


| P/N | Description | Qty. |
|-------------|---------------------------|------|
| L4421-84303 | L44xxA Power Rating Label | 1 |

ADMINISTRATIVE INFORMATION

| | | |
|---|--|---|
| SERVICE NOTE CLASSIFICATION: MODIFICATION RECOMMENDED | | |
| ACTION X ON SPECIFIED FAILURE CATEGORY: <input type="checkbox"/> AGREEABLE TIME | STANDARDS LABOR: 0.5 Hours | |
| LOCATION X CUSTOMER INSTALLABLE CATEGORY: <input type="checkbox"/> ON-SITE (active On-site contract required) X SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER | SERVICE X RETURN INVENTORY: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT | USED X RETURN PARTS: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT |
| AVAILABILITY: PRODUCT'S SUPPORT LIFE | NO CHARGE AVAILABLE UNTIL: End of Support | |
| <input type="checkbox"/> Calibration Required X Calibration NOT Required | PRODUCT LINE: BL AUTHOR: TP | |
| ADDITIONAL INFORMATION: | | |

Situation:

It has been found that the instruments with affected serial numbers listed above have incorrect information printed on the power rating label. The instrument does NOT support 400 Hz operation at 100-127V.

**Solution/Action:**

Order a L4421-84303 L44xxA Power Rating Label and apply it over the existing power rating information on the instrument. After applying the L4421-84303 label, it should look similar to the picture below.

**Revision History:**

| Service Note Revision | Date | Author | Reason For Change |
|-----------------------|------------|--------|-------------------|
| 01 | 2015-07-02 | TP | As published |