

PRIORITY SAFETY – REQUIRES IMMEDIATE REPAIR ACTION AND SPECIAL EFFORT TO CONTACT CUSTOMERS

SJ50-09-S

S E R V I C E N O T E

Supersedes:
None

Agilent SJ50+ 1.2M (Series 0 and Series 1 Systems) Optical Board Test System

Serial Numbers: IE 11607325 – IE 42200003

POSSIBLE SERIOUS INJURY

WARNING

Pinch Hazard accessible through the side openings of the system

To Be Performed By: Agilent-Qualified Personnel Only

Parts Required:

P/N	Description	Qty.
5186-5440	SJ safety upgrade kit	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
PRIORITY SAFETY		
ACTION CATEGORY: IMMEDIATELY	STANDARDS: LABOR: 1.0 Hours	
LOCATION CATEGORY: ON-SITE	SERVICE INVENTORY: SCRAP	USED PARTS: SCRAP
AVAILABILITY: End Of Support		
AUTHOR: Martin Boyce	PRODUCT LINE: 80	
ADDITIONAL INFORMATION: 5186-5440 is orderable through SPD (SERVICE PARTS DELIVERY) at 1-800-816-8650.		
Reference the service note number in the activity description field of the SR.		

© AGILENT TECHNOLOGIES, INC. 2005
PRINTED IN U.S.A.



March 16, 2005

Situation:

If the SJ50+ has power applied and service personnel or operators access the inside of the system through the side openings, their hand can be caught in the Gantry, causing severe injury.

Solution/Action:

To install Safety Guards to protect against potential pinch hazard points on the SJ50+ system.

To install the gantry safety guard kits and follow the Installation Procedure 5186-5438 included in the "Safety Guard Kit" 5186-5440.

Note:

Once you have completed the installation of the "Safety Upgrade Kit" fill out and install the Service Note label (Part Number N7200-84366) on the SJ50+ System near the serial number plate at the rear of the machine.

After completion of this Service Note send an email with the SJ50+ Serial number and state the Service Note Identification Number to: MTBUSERVICENOTES@agilent.com