

Z2160A195-01

Safety Service Note

Implemented During
Normal Course of
Providing Support

Supersedes:
[NONE]

Z2160A-195- 2D MPAC Pro for FR1 4x4 functional throughput and FR2 2x2 Testing

Serial Numbers: TW45220201, TW45222301, TW45224601, TW45230501, TW45232401,
TW63110004, TW63110009, TW45222001, TW45222501, TW45221301, TW45221401, TW45222502,
TW45220801, TW45223901

POSSIBLE “CUT INJURY” HAZARD

WARNING

HAZARD CLASS 2

The Problem – Door handle used on chamber’s door potentially has sharp edge that can cause a hand laceration on operator

Parts Required:

1520-0734

ADMINISTRATIVE INFORMATION

ACTION	<input type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS	
CATEGORY:	<input checked="" type="checkbox"/> AGREEABLE TIME	LABOR: 2 Hours	
LOCATION	<input type="checkbox"/> SERVICE CENTER	SERVICE:	<input type="checkbox"/> RETURN
CATEGORY:	<input checked="" type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	<input type="checkbox"/> SCRAP
	<input type="checkbox"/> CHANNEL PARTNERS		<input type="checkbox"/> SEE TEXT
AVAILABILITY:	EOS	NO CHARGE AVAILABLE UNTIL:	ALWAYS
	<input type="checkbox"/> Calibration Required	PRODUCT LINE:	[PL13]
	<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR:	[P.U]

ADDITIONAL INFORMATION:

Situation:

It was reported that one door handle used for the door of our 2DMPAC pro chamber has a sharp edge that has caused a hand laceration on the end user during normal operation of the door

Solution/Action:

Support Engineering has followed PSE process. The resolution of the process is to add a rubber cushion sleeve as an available upgrade to customer entitled. It will be created as a KPN and will be deployed to selected serials of Z2160A-195 2D Multi-Probe Anechoic Chamber (MPAC) Pro chambers to cover the handles and eliminate the future potential risk.

Revision History:

Date	Service Note Revision	Author	Reason for Change
06 Sep 2024	01	Patricio Ugarte Garcia	As Published