

# Safety Service Note

Implemented During  
Normal Course of  
Providing Support

Supersedes:  
[NONE]

## Z2160A-1L8- 2D MPAC Pro for FR1 4x4 functional throughput and FR2 2x2 Testing

Serial Numbers: TW45224002, TW45224201, TW45224801, TW45230101, TW45223301, TW45224001

### POSSIBLE “CUT INJURY” HAZARD

**WARNING**

HAZARD CLASS 2

**The Problem** – Door handle used on chamber’s door potentially has sharp edge that can cause a hand laceration on operator

**Parts Required:**  
1520-0734

### ADMINISTRATIVE INFORMATION

ACTION		STANDARDS	
CATEGORY:	<input type="checkbox"/> ON SPECIFIED FAILURE	LABOR: 2 Hours	
	<input checked="" type="checkbox"/> AGREEABLE TIME		
LOCATION	<input type="checkbox"/> SERVICE CENTER	SERVICE:	<input type="checkbox"/> RETURN
CATEGORY:	<input checked="" type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	<input type="checkbox"/> SCRAP
	<input type="checkbox"/> CHANNEL PARTNERS	<input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY: EOS		NO CHARGE AVAILABLE UNTIL: ALWAYS	
<input type="checkbox"/> Calibration Required		PRODUCT LINE: [PL13]	
<input checked="" type="checkbox"/> Calibration NOT Required		AUTHOR: [P.U]	

ADDITIONAL INFORMATION:

**Situation:**

It was reported that one door handle used for the door of our 2DMPAC pro chamber has a sharp edge that has caused a hand laceration on the end user during normal operation of the door

**Solution/Action:**

Support Engineering has followed PSE process. The resolution of the process is to add a rubber cushion sleeve as an available upgrade to customer entitled. It will be created as a KPN and will be deployed to selected serials of Z2160A-1L8 2D Multi-Probe Anechoic Chamber (MPAC) Pro chambers to cover the handles and eliminate the future potential risk.

**Revision History:**

Date	Service Note Revision	Author	Reason for Change
06 Sep 2024	01	Patricio Ugarte Garcia	As Published