

MODIFICATION RECOMMENDED –
CORRECTS MANUFACTURING OR DESIGN DEFECTS

Z4215B-01

S E R V I C E N O T E

Supersedes:
None

Agilent Z4215B Laser Reference Cable

Serial Numbers: Non-serialized

Recommend replacement of cables due to improper grounding

To Be Performed By: Customer

Parts Required:

P/N	Description	Qty.
Z4215-60203	Replacement cable	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR: 0.0 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL:	
AUTHOR: JWE[initials]		PRODUCT LINE: 45[product line]	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2003
PRINTED IN U.S.A.



April 14, 2003

Situation:

It has been found that some cables with revisions “A” or “B” may not have continuous ground connection at the “Y” junction. This may cause susceptibility to system glitches.

Solution/Action:

Agilent will replace any Revision “A” or “B” cables with revision “C”, as P/N Z4215-60203 .
Considered warranty for all returned cables.