

SAFETY – IMPLEMENTED DURING NORMAL COURSE
OF PROVIDING SUPPORT

Z5623A-K66-01A-S

S E R V I C E N O T E

Supersedes:
Z5623A-K66-01

Z5623A opts K44, K64, K66

Serial Numbers: US01119414, 484, 485, 525, 526, 562, 566, 567, 572, 590

Potential FIRE HAZARD

WARNING

The units with the above serial numbers may have been shipped with an incorrect line module. These units should be checked and the line module replaced, if necessary.

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

P/N	Description	Qty.
-----	-------------	------

(See document Z5623-90083 available at URL:
http://na.tm.agilent.com/pna/z5623_90083.pdf)

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
SAFETY			
ACTION CATEGORY:	<input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR: 1.0 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	as needede	AGILENT RESPONSIBLE UNTIL: until units checked	
AUTHOR: L. S. Hall	PRODUCT LINE: WN		
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2006
PRINTED IN U.S.A.



October 20, 2006

Situation:

Some Z5623A multiport test sets may have been shipped with a line module rated for 1 amp instead of the intended 10 amps. There are only ten units that possibly have this problem. The serial numbers are listed above. Each unit needs to be checked and corrected, if necessary. There is a very small risk of this situation causing any problem that the user can detect.

Solution/Action:

The instructions for checking and correcting the problem are contained in the document Z5623-90083, available at the URL given above. The factory is contacting all present “owners” of the ten units and arranging for the needed service. Contact Lachlan Hall, telnet 577-4273, if you have any questions.