Information Only Service Note

U9403A Mini ICT SYSTEM

Serial Numbers: ALL
Manufacturing ID Number: N/A

The Problem

The controller's serial ports are not supported in Mini ICT system (U9403A)

Parts Required:

P/N   Description   Qty.
NONE

ADMINISTRATIVE INFORMATION

[[]] Calibration Required	PRODUCT LINE: 80
x Calibration NOT Required	AUTHOR: Eric Xu

ADDITIONAL INFORMATION:

KEYSIGHT TECHNOLOGIES

Situation:

Due to design constraints, the controller's serial ports (COM1 and COM2) are not supported in Mini ICT system (U9403A).

Solution/Action:

The users are suggested to use external USB-to-RS232 converter adapter instead for their application.

Revision History:

Date	Service Note Revision	Author	Reason for Change
01 Ju1 2022	01	Eric Xu	As Published