

S E R V I C E N O T E

SUPERSEDES: None

16099A Test Fixture Adapter

Duplicate Service Notes: None

Modification to be used with the 16191A, 16192A, and 16193A

To Be Performed By: Customer

Parts Required:

Part No.	Qty.	Description
16099-40002	1	Disc
2200-0140	3	Screw (flat-head)

Situation:

The 16099A's top disc was fastened with pan-head screws. These screws obstruct a use with the test fixtures 16191A, 16192A, and 16193A. So the disc has been fastened with flat-head screws since November 1, 1993. This service note provides information to apply this change to the old 16099A.

Solution/Action:

Replace the disc and screws. Use thread sealant (PN 0470-0013) to fasten the disc with screws.

DATE: 23 November 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	AGREEABLE TIME	<input checked="" type="checkbox"/> PERFORMANCE ENHANCEMENT <input type="checkbox"/> SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	AVAILABLE UNTIL:
AUTHOR: KH	ENTITY: 3301	ADDITIONAL INFORMATION: