

 MODEL 175A OSCILLOSCOPE  
All Serials

Improved Sweep Operation

For improved sweep operation in the 175A Oscilloscope V106 should be a 6CL6 (1923-0066).

Change the stock number in the Replaceable Parts List from 1923-0030 to 1923-0066. This is a special 6CL6.

02523-1

8