

34401A-14A

S E R V I C E N O T E

Supersedes:
34401A-14

34401A 6 ½ Digit Digital Multimeter

Serial Numbers: Greater than MY47XXXX/SG47XXXX

The Situation- The 34401A has been updated with a more modern look. This update is purely cosmetic. There are no usability or firmware changes.

Parts Required:

P/N	Description	Qty.
New Part Numbers		
34401-86020	Bumper Kit	1
34401-40231	Front Panel	1
34401-43731	Power-on Push Rod	1
34401-43732	Front/Rear Push Rod	1
34401-45021	Handle	1
34401-80121	Chassis	1
34401-81932	Keypad	1
New Exchange Part Numbers		
34401-69204	SN: MY47XXXX Exchange	1
34401-69205	SN: SG47XXXX Exchange	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: <div style="text-align: center; font-weight: bold; font-size: 1.2em; margin-top: 10px;"> INFORMATION ONLY </div>
AUTHOR: LH PRODUCT LINE: SP
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007
PRINTED IN U.S.A.



September 10, 2007

Old Part Numbers

34401-86010	Bumper Kit	1
34401-40211	Front Panel	1
34401-43711	Power-on Push Rod	1
34401-43712	Frnt/Rear Push Rod	1
34401-45011	Handle	1
34401-80111	Chassis	1
34401-81912	Keypad	1

** New parts are not compatible with the Old parts/units. Old 34401A units can be upgraded to modern look by purchasing all of the new parts.