

37711A-03

S E R V I C E N O T E

SUPERSEDES: None

HP 37711A T1/Datacom Test Set

Serial Numbers: 0000U00000/9999U99999

Duplicate Service Note: 37701A-03

Option 001 can be retrofitted.

Situation:

Option 001 which gives a Pulse Shape measurement capability can be retrofitted by ordering an upgrade kit.

Solution/Action:

Order retrofit kit HP Part Number 37701-60041. The kit contains all of the parts and procedures to retrofit and test the upgrade.

DATE: 29 July 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	AGREEABLE TIME	<input checked="" type="checkbox"/> PERFORMANCE ENHANCEMENT <input type="checkbox"/> SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> HP LOCATION	AVAILABLE UNTIL:
AUTHOR: ER	ENTITY: 1400	ADDITIONAL INFORMATION: