

37721A-04

S E R V I C E N O T E

SUPERSEDES : None

HP 37721A Digital Transmission Analyzer

Serial Numbers:3015U00101 / 3123U00666

Replacement of Battery

In the event of Battery failure in the HP 37721A, the Battery on the A3 Assembly should be replaced by Retrofit Kit P/N 37721-60043.

Retrofit Kit p/n 37721-60043, contains the following parts:

HP Part No.	Qty.	Description
1420-0315	1	Battery
37721-60038	1	Battery Holder
37721-00038	1	Bracket
0515-1430	2	Screw (Countersunk)
0515-0897	2	Screw
0535-0025	2	Nut
3050-0003	2	Fibre Washer
0360-1788	2	Test Pin
37721-90043	1	Modification Procedure

DATE: 29 October 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ IMMEDIATELY ☒ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR: 2.0 Hours	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☒ HP LOCATION	SERVICE INVENTORY: ☐ RETURN ☐ SCRAP ☐ SEE TEXT	USED PARTS: ☐ RETURN ☐ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		
AUTHOR: JH	ENTITY: 1400	RESPONSIBLE ENTITY: 1400 UNTIL: 31 July 1993	
		ADDITIONAL INFORMATION:	

© 1991 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.

