

3785A-26

S E R V I C E N O T E

SUPERSEDES: None

HP 3785A Jitter Generator Receiver

Serial Numbers: 0000U00000 / 9999U99999

Situation:

1853-0034 is being discontinued by Motorola. Alternative part 1853-0007 is to be used.

Modify Material Lists: 03785-60030
03785-60032
03785-60232
03785-60223

Delete: 1853-0034

Add: 1853-0007

DATE: May 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

SM

1400

© 1994 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.

