


S E R V I C E N O T E

SUPERSEDES: NONE

3852A Data Acquisition/Control Unit**Serial Numbers:** 2927A00000 / 2927A12048**Incorrectly Labeled Line Voltage Switches May Cause Switch Setting Confusion****Situation:**

Some units may have incorrectly labeled line voltage selection switches installed. The correct settings appear silkscreened on the instrument rear panel. The incorrect settings are silkscreened on the voltage selection switches themselves.

**Figure 1. AC Line Voltage Switch Positions****Solution/Action:**

No action is required. However, to avoid confusion, the incorrectly silkscreened line voltages may be easily scratched off using a flat-head screwdriver.

DATE: 09 September 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

CMC

ENTITY:

0900

ADDITIONAL INFORMATION: